E R R O R M E M O R Y R E P O R T

.....

Date: 04/10/14 10:32:30

VIN: ABCMAZE

Identification: 3B2F

Customer: ABCMAZE

RESULT: 4 errors in error memory :

---

1) wheel speed sensor front left trigger signal

Error frequency : 0

vehicle speed	0.00	km/h
system actic	0.00	.
brake lights switch	0.00	.