

Errorcode: EE BB 01 28 BA 16 12 11 A7 6A

---

239 burning fail Cylinder 2

Error frequency : 1

Logistic counter: 40

TCO	93.00	Grad C
N_32_TOL	736.00	rpm
MAF_TOL	141.62	mg/stk
MAF_BOL	92.60	mg/stk
aufgetreten vor (rel. BZ)	0.20	h

---

Misfire CARB\_B1

---

FUS active to Failure entry

Error to relevant

Error debounce

Error currently not available

sporadic Error

Errorcode: EF BA 01 28 BC 17 1A 11 A7 6A

---

Errorcode: 99 B4 01 28 75 08 FF 51 A7 6A

---

238 burning fail Cylinder 1

Error frequency : 1

Logistic counter: 40

TCO	91.50	Grad C
N_32_TOL	704.00	rpm
MAF_TOL	98.05	mg/stk
MAF_BOL	92.60	mg/stk
aufgetreten vor (rel. BZ)	0.20	h

Misfire CARB\_A

Misfire CARB\_B1

---

FUS active to Failure entry

Error to relevant

Error debounce

Error currently not available

sporadic Error

Errorcode: EE BB 01 28 BA 16 12 11 A7 6A

---